

## QUICK INSTALL GUIDE - WinPCSIGN Pro 2007

Be sure to close all open programs and insert the CD-ROM program into the CD-ROM or DVD drive.  
If the autorun is active you will see the presentation screen.  
If you wish to install WinPCSIGN Pro 2006 program click the INSTALL button.


Step 1: Install program

Step 2: Install the software of the key

Step 3: Place the security key in an available USB port


Step 4: Run the program and configure your vinyl cutter

Step 5: Test your cutter.



Or

C:\Program Files\SignMAX\WinPCSIGN Pro 2006 suite



Install the key Rockey4 in an available USB port.



Now you can run the WinPCSIGN program and configure your cutter.